

Product Type	XLR Plug	
Product Model	SCMM5-BG	
Customer Name		

Manufactuur	Prepared	Checked	Approved
Manufacturer			

0 1	Received	Checked	Confirmed
Customer			



Phone: 407-857-8770 Fax: 407-857-8771 Email: sales@techni-lux.com

www.techni-lux.com





Product Type	XLR Plug	are out
Product Model	SCMM5-BG	

Product Features

- 5-core XLR male cable connector with black plated housing and gold plated contacts
- The metal housing adopts internal thread design to ensure that it can withstand gravity under any site conditions
- Two cable clamps are provided for different cable diameters; black clamp 3.5-6mm; white clamp 6-8mm
- > No ring design which is more compact and can save space
- Colored boots available for coding or identification
- The boot is equipped with a polyurethane sealing sleeve to prevent the cable from being affected by bending pressure to the greatest extent



Product parameters

Item	Specification
Connection Type	XLR
Gender	Male

Electrical Parameters

Item	Specification
Capacitance between contacts	≤ 7pF
Contact resistance	≤ 3 mΩ
Dielectric strength	1.5 kV DC
Insulation resistance	> 10 GΩ (initial)
Rated current per contact	7.5 A
Rated voltage	< 50 V



Mechanical Parameters

Item	Specification
Cable O.D.	Black strain relief: 3.5-6 mm White strain relief: 6-8 mm
Insertion force	≤ 20 N
Withdrawal force	≤ 20 N
Service life	> 1000 mating cycles
Cable size	Max.1.0 mm ² Max.18 AWG
Locking device	Latch lock



Material and Environmental Parameters

Item	Specification
Boot	PA
Contacts	Cu alloy
Contact plating	Au
Insert	PA
Housing	Zinc diecast
Housing plating	Black
Strain relief	РОМ
Flame-retardant grade	UL 94 HB
Protection class	IP40
Temperature range	-30°C ~ +80°C

Standards and Certifications

Standards	IEC 61076-2-103
Solderability	Complies with IEC 68-2-20



61.00±0.30 61.00±0.30 61.00±0.30

Unit: mm

Packaging Method

1 pc per bag (include 1 pc each of inner core assembly, housing, black and white cable clamps, boot) 80 pcs per inner carton, 5 inner cartons per master carton (or 400 pcs per master carton)

Accessory

- ☑ No accessories
- ☐ Screws and Nuts

- ☐ Back fastener plate
- □ Other



Assembly Instructions

(1) Put the cable through the boot	
(2) Strip the cable in the size as shown	4.00
(3) Insert the conductor of the cable into the terminal of the inner core and solder	
(4) Insert cable into the clamp and snap into inner core assembly bayonet	



(6) After the assembly of the clamp, inner core component and housing, tighten the boot in a clockwise direction.